

the play inspection company

Annual Inspection

St Albans City and District Council

Roestock Park

Admirals Close, Colney Heath, AL4 0QD











Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL t- 01202 590675 e- info@playinspections.co.uk





RPII Inspection Methodology

This document outlines the RPII position on inspections undertaken by the Inspectors listed on the RPII Register of Inspectors for Indoor Annual, Outdoor Operational and Outdoor Routine.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it the date of the standard will be that current at the time of inspection with the exception of where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this would include public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below);

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, including ancillary items).

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standard (BS EN 71 – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance within the inspection will still refer to BS EN 1176.

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

BS EN 15312 - Free access multi-sports equipment

BS EN 14974 - Skateparks

BS EN 16630 - Permanently installed outdoor fitness equipment

BS EN 16899 - Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with current standards and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area up to 3.0 metres around, or the fence line if closer.

Operational inspections only take into consideration defects related to wear and vandalism. Routine visual inspections (if undertaken) relate only to the most obvious defects such as broken or missing parts, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

The inspection is non-dismantling, non-destructive and does not include for any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all standing surfaces as necessary on the equipment and assess all parts up to 2.5m above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment. Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document to ensure as far as is reasonably practicable the continued safe use of the items concerned. The owner/operator is responsible for the overall safety of the equipment and area. Inspectors who are trained to use ladders may use them where it is safe to do so, but if members of the public are present on-site ladders may not be used to access the equipment.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of impact absorbing properties of any surfaces. The identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection or the inspection of any equipment (or part thereof) that is underground. Tightening any bolts, hinges or other fixing devices on any apparatus or equipment. Assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment. Assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming).

Where planting or trees are mentioned in the report no aboricultural or horticultural assessments of toxicity, suitability or condition are undertaken; the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity and this inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/ or that of the inspection company. The owner/operator should seek the advice of the manufacturer or a competent person at all times when undertaking repairs and/or modifications to equipment.

A full copy of the Play Inspection Company Ltd. Terms & Conditions is available on our website (www.playinspections.co.uk)

© The Play Inspection Company & the Register of Play Inspectors International 9th September 2020





Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual Outdoor/ Fully enclosed Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	V	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	V	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	V	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	~	✓ [3]
6.1 d) Effects of weather	V	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	V	✓ [4]
6.1 d) Excavation or dismantling/additional measures	V	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	V	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	V	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

- [1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.
- [2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.
- [3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.
- [4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance
- [5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Severity						
			Severity>>						
	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)	
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)	
Likelihood	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)	
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)	
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)	
		•		Very Low	Low	Moderate	High	Very High	
	Pi			1	2	3	4	5	
				No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality	
	Severity>>								

Note 1: The total risk scores included within our reports are a multipication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Equipment has been assessed to the following standards where relevant:

BS EN 1176 Parts 1-11 (Playground equipment and surfacing)

BS EN 14974 (Facilities for users of roller sports equipment)

BS EN 15312 (Free access multi-sports equipment)

BS EN 16899 (Parkour Equipment)

BS EN 16630 (Outdoor Fitness Equipment).



Roestock Park

Inspection Ref: 1294387 Site Ref: 77680

Inspected: 17-February-2021 - 11:38 by David Fagan (RPII Annual Inspector)

Risk Assessment: 8 Low Risk



Location:

The site is located in an area of public open space and is not directly overlooked by any properties in the local community.

Disabled Access:

Generally accessible; an area accessible to most.





4 - Very Low Risk

Item:Gate - Self ClosingManufacturer:Not IdentifiedSurface Type:Bitmac

Item Quantity:1Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -



6 - Low Risk

Item:Fencing - Flat TopManufacturer:Owner/Operator

Surface Type: Grass Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

The paint is flaking off the metalwork - Rub down and re-

paint

Finding 2

There is some damage to the fence sections - Monitor for any further deterioration and repair as required





4 - Very Low Risk

Item:Litter BinManufacturer:Not Identified

Surface Type:GrassItem Quantity:1Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -



8 - Low Risk

Item:BenchManufacturer:Not Identified

Surface Type: Grass Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

The area around the item has eroded and may become slippery - Reinstate eroded area





6 - Low Risk

Item: Sign

Manufacturer: Owner/Operator

Surface Type: Grass Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required

BS EN 1176 Part 7 recommends that signage shall include the site name / address - Provide additional information

Finding 2



6 - Low Risk

Item:SupanovaManufacturer:Kompan LtdSurface Type:Grass Matrix Tiles

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 1



Finding 1

The surface has eroded in some areas - Reinstate the surface





6 - Low Risk

Surf Swing Item: Manufacturer: Hags

Surface Type: **Grass Matrix Tiles**

Item Quantity: 1 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Total Findings: 1



Finding 1

The surface has eroded in some areas - Reinstate the surface



6 - Very Low Risk

Item: Multi Use Games Area (MUGA)

Manufacturer: Zaun Fencing

Surface Type: Bitmac **Item Quantity:** 1 **Equipment Compliance:** No Surface Area Compliance: N/A

Total Findings: 2



Finding 1

There is/are missing fixings creating finger entrapments in the surround and the item fails to meet the requirements of BS EN 15312 Clause 4.4.2.2 Entrapment of fingers -Replace the missing fixings to remove the entrapment from the equipment

Finding 2

A clearly visible facility sign should be provided in a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - the warning - the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident -Provide signage to BS EN 15312



8 - Low Risk

Item: Roundabout

Manufacturer: Other

Surface Type: Grass Matrix Tiles

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 2

Finding 2

There are gaps opening between the grass mat tiles -

Reinstate surface

Finding 1

The bearing is not operating correctly - Repair or replace

the bearing as required

9

5 - Very Low Risk

Item:Dish RoundaboutManufacturer:Sutcliffe Play LimitedSurface Type:Grass Matrix Tiles

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 1



Finding 1

Fixing Pins have been installed in the impact areas of the grass mats - Remove pins from impact areas





6 - Low Risk

2 Bay 2 Flat 1 Cradle Seat Item:

Not Identified Manufacturer: **Grass Matrix Tiles Surface Type:**

Item Quantity: Equipment Compliance: Nο Surface Area Compliance: Yes

Total Findings: 3



Finding 1

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work any further deterioration and replace when 40% worn recommended

Finding 3

BS EN 1176 Part 2: Annex A makes a recommendation that fences or enclosures should be upto 1m from the edges of the swing seat to the sides, and subject to risk assessment, from the edge of the impact area. This is however, a low risk finding and no remedial action is recommended. - Monitor -No remedial work recommended

Finding 2

There is some notable evidence of chain wear - Monitor for

6 - Low Risk

Item: Multi Play (Junior) Safe & Sound Manufacturer: **Surface Type: Grass Matrix Tiles**

Item Quantity: Equipment Compliance: No Surface Area Compliance: Yes

3 **Total Findings:**



Finding 1

The unit is easily accessible and has an opening in the barrier to steep play elements in excess of 500mm in contravention of BS EN 1176 Part 1 - Monitor - No remedial work recommended

Finding 3

There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

Finding 2

There is/are several inserts missing - Replace missing inserts





Findings information





Item:Fences - Fencing - Flat TopRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Grass



Finding: There is some damage to the fence sections



Action: Monitor for any further deterioration and repair as required









become slippery

Item:Ancillary Items - SignRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Grass







Action: Monitor for any further deterioration and repair as required







5 - Very Low Risk (Finding 2)

Item: Ancillary Items - Sign Risk Level: V - Very Low Risk

Manufacturer: Owner/Operator Surface: Grass





Finding: BS EN 1176 Part 7 recommends that signage shall **Action:** Provide additional information include the site name / address

6 - Low Risk (Finding 1)

Item:Rotor Play - SupanovaRisk Level:L - Low RiskManufacturer:Kompan LtdSurface:Grass Matrix Tiles





Finding: The surface has eroded in some areas

Action: Reinstate the surface











5 - Very Low Risk (Finding 1)

Multi Use Games Area - Multi Use Games

Manufacturer: Area (MUGA)

Zaun Fencing

Risk Level: V - Very Low Risk

Surface: Bitmac







Finding: There is/are missing fixings creating finger entrapments in the surround and the item fails to meet the requirements of BS EN 15312 Clause 4.4.2.2 Entrapment of fingers

Action: Replace the missing fixings to remove the entrapment from the equipment







5 - Very Low Risk (Finding 2)

Multi Use Games Area - Multi Use Games Item:

Area (MUGA) Manufacturer: Zaun Fencing Risk Level: V - Very Low Risk

Surface: Bitmac





Finding: A clearly visible facility sign should be provided in Action: Provide signage to BS EN 15312 a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident

8 - Low Risk (Finding 1)

Rotor Play - Roundabout Item:

Manufacturer: Other Risk Level: L - Low Risk Surface: **Grass Matrix Tiles**





Finding: The bearing is not operating correctly


Action: Repair or replace the bearing as required





of the grass mats





Annual Inspection for St Albans City and District Council at Roestock Park Admirals Close, Colney Heath, AL4 0QD Inspected on the 17-February-2021 - 11:38







Item: Swings - 2 Bay 2 Flat 1 Cradle Seat Risk Level: V - Very Low Risk Manufacturer: Not Identified Surface: Grass Matrix Tiles





Finding: The chain openings are in excess of the 8.6mm as **Action:** Monitor - No remedial work recommended recommended by BS EN 1176

6 - Low Risk (Finding 2)

Item: Swings - 2 Bay 2 Flat 1 Cradle Seat

Manufacturer: Not Identified



Finding: There is some notable evidence of chain wear

Risk Level: L - Low Risk
Surface: Grass Matrix Tiles



Action: Monitor for any further deterioration and replace when 40% worn







Item: Swings - 2 Bay 2 Flat 1 Cradle Seat

Manufacturer: Not Identified



Finding: BS EN 1176 Part 2: Annex A makes a recommendation that fences or enclosures should be upto 1m from the edges of the swing seat to the sides, and subject to risk assessment, from the edge of the impact area. This is however, a low risk finding and no remedial action is recommended.

Risk Level: L - Low Risk
Surface: Grass Matrix Tiles



Action: Monitor - No remedial work recommended







Item:Activity Equipment - Multi Play (Junior)Risk Level:L - Low RiskManufacturer:Safe & SoundSurface:Grass Matrix Tiles








Finding: The unit is easily accessible and has an opening in **Action:** Monitor - No remedial work recommended the barrier to steep play elements in excess of 500mm in contravention of BS EN 1176 Part 1





Finding: There is/are several inserts missing



Action: Replace missing inserts





